

1: Power Supply Board Revised: Monday, August 13, 2001
2: 100-1006 Revision: NC
3:
4: Drawn by Jim Patchell
5:
6:
7:
8:
9:

10: Bill Of Materials August 13,2001 19:59:54 Page1

11:

12: Item Quantity Reference Part Mouser Part Number

13: _____

14:

15: 1 2 C1,C3 4700uF 140-XRL35V4700
16: 2 3 C2,C4,C6 10uF 140-XRL25V10
17: 3 1 C5 10000uF 140-XRL16V10000
18: 4 12 D1,D2,D3,D4,D5,D6,D7,D8, 1N4004 625-1N4004
19: D9,D10,D11,D12
20: 5 4 JP1,JP2,JP3,JP4 HEADER 4 538-26-48-1245
21: 6 1 U1 LM7815 511-L7815CT
22: 7 1 U2 LM7915 511-L7915CT
23: 8 1 U3 LM7805 511-L7805CT
24: